

Product Security Bulletin

IMPORTANT INFORMATION - PLEASE READ AND KEEP

SentrySuite: Windows 10 Security Update Compatibility

Date: 12-JUL-2021 (last update)

Background

Microsoft is identifying Operating System (OS) and native Microsoft application level vulnerabilities which impact the Windows 10 OS which is part of the environment in which Vyaire Medical's SentrySuite software runs.

While these vulnerabilities do not impact SentrySuite software directly, changes made by Microsoft to remediate these issues may cause compatibility issues with SentrySuite.

How Microsoft Is Responding

Microsoft regularly publishes new builds for its Windows 10 OS, called Quality Updates. The Quality Updates may contain important security patches for vulnerabilities in the Windows 10 OS. An overview of Windows 10 Quality Updates may be found here: <u>Windows 10 update history</u>.

How Vyaire Is Responding

Vyaire's SentrySuite software has been validated for use with Microsoft Windows 10 version **20H1** (2004) and **20H2**.

As Microsoft releases new Quality Updates for Windows 10 20H1 and 20H2, each version of SentrySuite compatible with Windows 10 which is not considered End-Of-Life is tested for compatibility with those new updates.

Each Quality Update contains the cumulative changes of all previously released updates. Testing of Quality Updates which are not security related maybe delayed.

This document will be regularly updated to reflect the outcome of Vyaire's compatibility tests and therefore provide a guideline which patches may be installed without compromising SentrySuite operation.



Product Security Bulletin IMPORTANT INFORMATION – PLEASE READ AND KEEP

Compatibility test results

Release date	Windows 10 build	Relevant Microsoft KB	Security updates in build	SentrySuite compatibility	Notes
06-JUL-2021 (out of band)	20H2: 19042.1083 20H1: 19041.1083	<u>KB5004945</u>	Yes	3.20.1 ✓ 3.10.5 ✓ 3.0.8 ✓	
08-JUN-2021	20H2: 19042.1052 20H1: 19041.1052	<u>KB5003637</u>	Yes	3.20.1 ✓ 3.10.5 ✓ 3.0.8 ✓	
11-MAY-2021	20H2: 19042.985 20H1: 19041.985	<u>KB5003173</u>	Yes	3.20.1 ✓ 3.10.5 ✓ 3.0.8 ✓	
13-APR-2021	20H2: 19042.928 20H1: 19041.928 1909: 18363.1500	KB5001330 KB5001330 KB5001337	Yes	3.20.1 ✓ 3.10.4 ✓ 3.0.7 ✓	See (4)
09-MAR-2021	20H1: 19041.867 1909: 18363.1440	KB5000802 KB5000808	Yes	3.20 ✓ 3.10.4 ✓ 3.0.7 ✓	
09-FEB-2021 11-FEB-2021	20H1: 19041.804 1909: 18363.1379	KB4601319 KB5001028	Yes	3.20 ✓ 3.10.3 ✓ 3.0.6 ✓ 2.21.6 ✓	
08-DEC-2020	1909: 18363.1256 1903: 18362.125	<u>KB4592449</u>	Yes	3.10.3 ✓ 3.0.6 ✓ 2.21.6 ✓	See (3)
13-OCT-2020	1909: 18363.1139 1903: 18362.1139	<u>KB4577671</u>	Yes	3.10.3 ✓ 3.0.6 ✓ 2.21.6 ✓	
16-SEP-2020	1909: 18363.1110 1903: 18362.1110	<u>KB4577062</u>	No	3.10.3 ✓ 3.0.6 ✓ 2.21.6 ✓	

RECONLY For global distribution.

^{© 2021} Vyaire. Vyaire and the Vyaire logo and all other trademarks or registered trademarks are property of Vyaire Medical, Inc., or one of its affiliates. Medical devices class IIb according to Medical Devices Directive 93/42/EEC. Please read the complete Instructions For Use that come with the devices or follow the instructions on the product labelling. | VYR-GBL-2100030



Product Security Bulletin IMPORTANT INFORMATION – PLEASE READ AND KEEP

Release date	Windows 10 build	Relevant Microsoft KB	Security updates in build	SentrySuite compatibility	Notes
08-SEP-2020	1909: 18363.1082 1903: 18362.1082	<u>KB4574727</u>	Yes	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
20-AUG-2020	1909: 18363.1049 1903: 18362.1049	<u>KB4566116</u>	No	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
11-AUG-2020	1909: 18363.1016 1903: 18362.1016	<u>KB4565351</u>	Yes	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
21-JUL-2020	1909: 18363.997 1903: 18362.997	<u>KB4559004</u>	No	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
14-JUL-2020	1909: 18363.959 1903: 18362.959	<u>KB4565483</u>	Yes	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
16-JUN-2020	1909: 18363.904 1903: 18362.904	<u>KB4567512</u>	No	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
09-JUN-2020	1 909: 18363.900 1903: 18362.900	<u>KB4560960</u>	Yes, see <u>Microsoft</u> <u>Security</u> <u>Update Guide</u>	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	See (2)
12-MAY-2020	1 909: 18363.836 1903: 18362.836	<u>KB4556799</u>	Yes, see <u>Microsoft</u> <u>Security</u> <u>Update Guide</u>	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
21-APR-2020	1 903: 18362.815	<u>KB4550945</u>	No	3.10.2 ✓ 3.0.5 ✓ 2.21.6 ✓	
14-APR-2020	1 903: 18362.778	<u>KB4549951</u>	Yes, see <u>Microsoft</u> <u>Security</u> <u>Update Guide</u>	3.10.2 ✓ 3.0.5 ✓ 2.21.5 ✓	

For global distribution. © 2021 Vyaire. Vyaire and the Vyaire logo and all other trademarks or registered trademarks are property of Vyaire Medical, Inc., or one of its affiliates. Medical devices class IIb according to Medical Devices Directive 93/42/EEC. Please read the complete Instructions For Use that come with the devices or follow the instructions on the product labelling. | VYR-GBL-2100030



Product Security Bulletin IMPORTANT INFORMATION – PLEASE READ AND KEEP

Release date	Windows 10 build	Relevant Microsoft KB	Security updates in build	SentrySuite compatibility	Notes
30-MAR-2020	1 903: 18362.753	KB4554364	No	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	
24-MAR-2020	1 903: 18362.752	KB4551762	No	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	
12-MAR-2020	1 903: 18362.720	KB4551762	Yes, see <u>Microsoft</u> <u>Security</u> Update Guide	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	See (1)
10-MAR-2020	1 903: 18362.719	KB4540673	Yes, see <u>Microsoft</u> <u>Security</u> Update Guide	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	
27-FEB-2020	1 903: 18362.693	<u>KB4535996</u>	No	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	
11-FEB-2020	1 903: 18362.657	<u>KB4532693</u>	Yes, see <u>Microsoft</u> <u>Security</u> <u>Update Guide</u>	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	
28-JAN-2020	1 903: 18362.628	KB4532695	No	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	
14-JAN-2020	1 903: 18362.592	KB4528760	Yes, see <u>Microsoft</u> <u>Security</u> <u>Update Guide</u>	3.10.1 ✓ 3.0.4 ✓ 2.21.5 ✓	

Vyaire recommends installing any relevant security updates that have been tested as compatible per the compatibility test results table above.

Compatibility test notes

(1) Microsoft OneNote update is installed with this build and sets the default printer to OneNote. Default printer needs to be manually changed back to previously selected

Page 4 of 6



Product Security Bulletin

IMPORTANT INFORMATION - PLEASE READ AND KEEP

default printer. This does not affect SentrySuite.

- (2) Microsoft introduced an issue in this build which may cause issues with printing to a physical or virtual printer. Vyaire does not recommend installing this build but instead to install build 904, released by Microsoft on 16-JUN-2020 which mitigates this issue.
- (3) This will be the last Windows update released by Microsoft for Windows 10 1903. Windows 10 1903 has reached "End of Life" (EOL) status as of 08-DEC-2020
- (4) This will be the last Windows update released by Microsoft for Windows 10 1909. Windows 10 1909 has reached "End of Life" (EOL) status as of 11-MAY-2021.

SentrySuite and Windows 10 compatibility testing plan

All Windows 10 versions released by Microsoft have a defined "End of Life" (EOL) date after which Microsoft won't release any more quality or security updates for the version. For details and EOL dates, please see Microsoft's <u>Windows 10 release information website</u> and the <u>Windows</u> Lifecycle FAQ.

The following table explains which SentrySuite version is tested against which Windows 10 feature version:

Windows 10	Windows 10	Compatibility	SentrySuite Version			
Version	EOL date	test status	3.20	3.10	3.0	2.21
1803	12-NOV-2019	Tests stopped			х	x
1809	10-NOV-2020	Tests stopped			X	x
1903 (19 H1)	08-DEC-2020	Tests stopped 08-DEC-2020		x	х	х
1909 (19 H2)	11-MAY-2021	Tests stopped 13-APR-2021	X ¹	x	х	X ²
2004 (20 H1)	14-DEC-2021	Tests ongoing	х	Х	х	X ²
20 H2	10-MAY-2022	Tests ongoing	X	X	X	
21 H1	not yet released	On roadmap	X	X	х	
21 H2	not yet released	On roadmap	X	X		

¹Tests for Windows 10 1909 and SentrySuite 3.20 will commence once SentrySuite 3.20 has been released by Vyaire.

²Tests for SentrySuite 2.21 will be stopped after end of March 2021.

Page 5 of 6



Product Security Bulletin

IMPORTANT INFORMATION – PLEASE READ AND KEEP

Vyaire does not recommend using Windows 10 versions which have been marked as EOL by Microsoft.

These Windows 10 versions will not receive regular quality and security updates by Microsoft anymore any may be vulnerable to threats that emerged after the EOL date.

Generic controls

- Ensure your data has been backed up and stored according to your individual process and that your disaster recovery procedures are in place.
- Update your anti-virus and malware protection, where available.

For product or site-specific concerns, contact your Vyaire service representative.

For more information on Vyaire's proactive approach to product security and vulnerability management, contact us at productsecurity@vyaire.com or visit www.vyaire.com/product-security

Timo Kosig timo.kosig@vyaire.com Product Security Leader Vyaire Medical GmbH

Mon

Holger Schmitt holger.schmitt@vyaire.com Senior Product Manager Software and IT integration Vyaire Medical GmbH

GLOBAL HEADQUARTERS

Vyaire Medical, Inc. 26125 North Riverwoods Blvd Mettawa, IL 60045 USA

RECONLY For global distribution.

Vyaire Medical GmbH Leibnizstrasse 7 97204 Hoechberg Germany

AUSTRALIAN SPONSOR

Vyaire Medical Pty Ltd Suite 5.03, Building C 11 Talavera Road Macquarie Park, NSW, 2113 Australia

CE 0123

Page 6 of 6

© 2021 Vyaire. Vyaire and the Vyaire logo and all other trademarks or registered trademarks are property of Vyaire Medical, Inc., or one of its affiliates. Medical devices class IIb according to Medical Devices Directive 93/42/EEC. Please read the complete Instructions For Use that come with the devices or follow the instructions on the product labelling. | VYR-GBL-2100030